



May 20, 1985

RE: Phone Conversation
of 5/17/85 NF377A

United States Environmental Protection Agency
InterFirst Two Building
1201 Elm Street
Dallas, Texas 75270

~~PRECISION NATIONAL CORP~~

~~TXD056863708~~

Dear Sir:

This is to inform you of our correction of a problem that was found to exist on April 18, 1985. Several years ago some grinding swarf was dumped on our property which consisted of metals removed in our grinding process. Also a failure of the level control in our fume scrubber allowed a small amount of water used to scrub the fumes in our plant to overflow in this same location. This is the #13 location noted in your inspection.

The following work was done before your letter was received:
Concrete retaining walls were installed surrounding concrete pads on which these scrubbers sit. Pumps and drains allow any overflow to go to our treatment system.

The area where the dumping was done is to be dug up and the soil treated and disposed of at the local land fill. The practice of dumping was stopped many years ago. We do not dump or discharge any material other than to the public owned treatment system which is sampled each month by the City of Waco Water Pollution Control Abatement.

Thank you for your courtesy and prompt attention shown to us in this matter.

SUPERFUND FILE

Yours Truly,

JAN 12 1993


W.P. Mathews
W. P. MATHEWS
Regional Manager

REORGANIZED

WPM/jda

cc: Texas Department of Water Resources

90067075



370805026